

Arundel On The Bay
Community Roads Needing Repair

AOTB HOA BOD Repair Priority Order	Road	Block Location of Damage	Road Surface	Repair Description	Final Repair Cost
Contracted during fiscal year 2008	Sycamore	East of Narragansett	Gravel	Resurface with gravel.	
Contracted during fiscal year 2008	Sycamore	West of Rockway	Asphalt	Pot hole patch.	
1	Walnut	East of Narragansett	Asphalt	Resurface damaged asphalt. (Half of Walnut east of Narragansett is asphalt and half is gravel. The gravel portion is in pretty good shape and would not be effected.)	
2	Chestnut	Between Newport and Rockway	Asphalt	2 pot hole patches.	
3	Cedar	at Niagra	Asphalt	Curve from Cedar onto Niagra breaking up.	
4	Walnut	Between Saratoga and Newport	Asphalt	A number of small pot holes and road side breaking up.	
5	Chestnut	East of Rockway	Asphalt	Small pot hole.	
6	Hollywood	East of Narragansett	Gravel	Resurface with gravel and asphalt apron.	
7	Rockway	South of Walnut	Asphalt	Small pot hole.	
8	Myrtle	East of Narragansett	Gravel	Resurface with gravel and asphalt apron.	
Completed Fiscal Year 2009	Narragansett	South of Magnolia	Gravel	Fill in pot holes and resurface with gravel.	\$4,400
Completed Fiscal Year 2009	Cedar	East of Narragansett	Gravel	Fill in pot holes and resurface with gravel.	\$4,400
Completed Fiscal Year 2009	Narragansett	South of Magnolia	Asphalt	Collapsed drain pipe causing pot hole. Pipe would be pulled out and replaced and asphalt patch put in place.	\$2,400
Completed Fiscal Year 2009	Chestnut	East of Narragansett	Gravel	Fill in pot holes and resurface with gravel.	\$4,700
Completed Fiscal Year 2009	Magnolia	West of Saratoga	Gravel	Fill in pot hole, grade for drainage and resurface with gravel.	\$3,100
Completed Fiscal Year 2008	Saratoga	North of Myrtle	Gravel	CR6 gravel used to resurface.	
Completed Fiscal Year 2008	Saratoga	Between Oak and Myrtle	Gravel	Asphalt pulled up and replaced.	